


FIG. 1 PRIOR ART



Best Available Copy

10083494.022702

FIG. 2




FIG. 3




FIG. 4





FIG. 5



202220-4648001

FIG. 6





FIG. 7



20220464E800

FIG. 8





FIG. 9



202220" 464E800T

73 FIG. 10





FIG. 11



20220164800T 10083494.022702

FIG. 12




FIG. 13




FIG. 14





FIG. 15



10083494.022702

FIG. 16




FIG. 17






FIG. 18




FIG. 19






FIG. 20



10083494.022702

FIG. 21



202220-464800T

FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26





FIG. 27



2027220-164E8002

FIG. 28




FIG. 29






FIG. 30



202204648802


204220" 464E800T

FIG. 31



202220" 164E8DDT

FIG. 32




16/44



20220" 464E800T


FIG. 33



17/44


202220" 464E800F

FIG. 34



20220" 464E800T

FIG. 35



19/44

FIG. 36






FIG. 38





FIG. 39



20220404.022702

↙ 731



✓ 731








FIG. 42



10083494.022702


FIG. 43



10033494.022702


20/220" H64E800T

FIG. 44




202220" 164E800T

FIG. 45




20220" HSEB00T

FIG. 46



202220" 164E300F


FIG. 47



31/44


20/220" t6HE800T

FIG. 48



1003494-022703


FIG. 49





202220" 464E800T


FIG. 50



34/44


202220" 464E800T

FIG. 51




20220" 164E800T

FIG. 52




202220" 464E800T

FIG. 53




20220-164E800F

FIG. 54




20220" 464E800T

FIG. 55




20220"468800T

FIG. 56



202220" 164E800T


FIG. 57






20220-464800T

FIG. 58




204220"464E800T

FIG. 59



20/220" 464E300T


FIG. 60



44/  
44

20/220" 464E800T

FIG. 61



**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☒ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** \_\_\_\_\_

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**